

### LEED INFORMATION

**PRODUCT:** HE869

**SS – CREDIT 7 / HEAT ISLAND EFFECT: ROOF**

This product does not meet the requirements of this credit.

**MR - CREDIT 4.x RECYCLED CONTENT**

RECYCLED CONTENT (POST-CONSUMER): 0%

RECYCLED CONTENT (POST-INDUSTRIAL): 0%

**MR - CREDIT 5.x– REGIONAL MATERIALS**

**EXTRACTION SITE:**

**Raw materials are sourced to Henry from various North American sources and extraction site of raw materials may vary without notice. As a result, the extraction site of materials used to manufacture this product is undetermined.**

**MANUFACTURING SITE(S): Garland TX 75042**

**MR- CREDIT 6 AND 7 – RAPIDLY RENEWABLE MATERIALS AND CERTIFIED WOOD**

This product does not contain rapidly renewable materials or certified wood.

**\* IEQ – CREDIT 4.1 – ADHESIVES AND SEALANTS**

Product not applicable to this credit.

**IEQ– CREDIT 4.2 – PAINTS AND COATINGS**

Product not applicable to this credit.

**VOC Content:** 500 g/L