

MANUFACTURER GUIDE DETAILS ARE FOR REFERENCE ONLY. HENRY DOES NOT ASSUME RESPONSIBILITY FOR ERRORS OF DEVIATIONS IN DESIGN OR ENGINEERING. PROJECT SPECIFIC VERIFICATION IS RECOMMENDED PRIOR TO INSTALLATION. HENRY CM100 AND PUMADEQ SYSTEM TIE IN

> CURB FLASHING CORNER FLASHING AT UPTURN HENRY CM100 AND PUMADEQ SYSTEM

R

999 N. Pacific Coast Highway, Suite 800

El Segundo, CA 90245

800-486-1278 • www.henry.com

CM100-TID-3C1